

Project Summary

Project Summary: Tanglewood Drive and Capwing Drive

Narrative Description of Project:

Completion: Oct-12

Project improved 1,922 L.F.of drainage system. Cleaned out 790 L.F. of valley drain and 1,012 L.F. of roadside ditch. Jetted (1) crossline pipe, (24) driveway pipes and 120 L.F of roadside pipe. Installed straw mat, handseeded and hydroseeded for erosion control.

2013-555 / Tanglewood Dr and Capwing Dr	Labor	Labor	Equipment	Material	Contractor	Indirect	
	Hours	Cost	Cost	Cost	Cost	Labor	Total Cost
AUDIT / Audit Project	1.0	\$20.89	\$0.00	\$0.00	\$0.00	\$13.23	\$34.12
COVD / Cleaned Out Valley Drains	15.0	\$313.40	\$59.36	\$22.82	\$0.00	\$138.25	\$533.82
DPJT / Driveway Pipe - Jetted	46.0	\$1,039.30	\$399.73	\$320.94	\$0.00	\$660.44	\$2,420.41
HAUL / Hauling	75.0	\$1,638.75	\$802.50	\$270.27	\$0.00	\$1,070.45	\$3,781.97
HYDR / Hydroseeding	8.0	\$170.96	\$28.52	\$67.98	\$0.00	\$110.60	\$378.06
ODBH / Outfall ditch - bushhogged	20.0	\$443.70	\$193.00	\$39.38	\$0.00	\$292.30	\$968.38
RB / Remove blockage from flowline	15.0	\$346.40	\$81.22	\$22.82	\$0.00	\$173.60	\$624.04
RSDCL / Roadside Ditch - Cleanout	65.0	\$1,510.95	\$497.78	\$145.97	\$0.00	\$1,028.40	\$3,183.10
RSPJ / Roadside Pipe - Jetted	14.0	\$305.83	\$155.12	\$47.55	\$0.00	\$115.29	\$623.79
UTLOC / Utility locates	1.0	\$20.89	\$0.00	\$0.00	\$0.00	\$13.23	\$34.12
2013-555 / Tanglewood Dr and Capwing Dr	290.0	\$6,473.27	\$2,364.43	\$965.80	\$0.00	\$4,052.29	\$13,855.79
Sub Total							

Grand Total	290.0	\$6,473.27	\$2,364.43	\$965.80	\$0.00	\$4,052.29	\$13,855.79










After





1 inch = 167 feet

Feet

Activity: Drainage Maintenance Project #: 2013-555 Township: Port **Royal Island Completed:** October 2012 Legend **Drainage Type** River Stream Outfall Lateral Lateral Pipe Roadside Roadside Pipe Crossline **D/W** Access Piped Bleeder

Date Print: 10/26/12 File:C:/sethdata/projects/projectmaps/Capwing Dr 2013-555