



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Iron Gate Subdivision

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Jul-14

Project improved 130 L.F. of drainage system. Cleaned out 130 L.F. of channel.

2015-509 / Iron Gate Subdivision	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	4.0	\$86.52	\$42.80	\$3.27	\$0.00	\$48.84	\$181.43
ODCO / Outfall ditch - cleaned out	9.0	\$184.10	\$50.62	\$13.08	\$0.00	\$82.95	\$330.75
ONJV / Onsite Job Visit	2.0	\$59.68	\$7.24	\$3.20	\$0.00	\$36.46	\$106.58
2015-509 / Iron Gate Subdivision Sub Total	15.5	\$340.53	\$100.66	\$19.55	\$0.00	\$174.87	\$635.61
 Grand Total	 15.5	 \$340.53	 \$100.66	 \$19.55	 \$0.00	 \$174.87	 \$635.61

Before



During



After



Project: Iron Gate Drive

**Activity: Routine/
Preventive
Maintenance**















**Project #:
2015-509**

**Township: Port
Royal Island**

**Completed:
July 2014**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



0 15 30 60 90 120
Feet

1 inch = 74 feet

Prepared By: BC Stormwater Management Utility

Date Print: 9/3/14

File: C:/sethdata/projects/projectmaps/Iron Gate Dr 2015-509