



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Pinewood Circle Channel #2

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 440 L.F. of drainage system. Cleaned out 440 L.F. of channel.

Completion: Apr-15

2015-597 / Pinewood Circle Ch #2	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CCO / Channel - cleaned out	15.0	\$331.60	\$136.98	\$23.65	\$0.00	\$220.80	\$713.03
UTLOC / Utility locates	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
2015-597 / Pinewood Circle Ch #2 Sub Total	16.0	\$352.06	\$136.98	\$23.65	\$0.00	\$234.03	\$746.72
Grand Total	16.0	\$352.06	\$136.98	\$23.65	\$0.00	\$234.03	\$746.72

Before



During



After



Project: Pinewood
Circle Channel #2

Activity: Routine/
Preventive
Maintenance

Project #:
2015-597














Township:
Port Royal Island

Completed:
April 2015



Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

Cleaned out 440 LF
of channel.

0 75 150 300 450 600
Feet

1 inch = 320 feet

Prepared By: BC Stormwater Management Utility

Date Print: 04/01/2015

File: C:\project summaries map\Pinewood Circle Channel #2_2015-597