Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Port Royal Island Vacuum Truck - Murray Drive, Blackburne Pierce Drive, Harold Drive, Campbell Road, Donaldson Drive, Peace Haven Drive and Roseida Road Extension Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 196 L.F. of drainage system. Cleaned out (16) catch basins. Jetted (7) crossline pipes, 150 L.F. of roadside pipe and 106 L.F. of channel pipe.

| 2015-306 / Port Royal Island Vacuum Truck | Labor Hours | Labor Cost | Equipment Cost | Material Cost | Contractor Cost | Indirect Labor | Total Cost |
|---|---|--|---|---|---|--|--|
| ADS / Administrative Support AUDIT / Audit Project CBCO / Catch basin - clean out CLJS / Cleaned up iobsite CLPJT / Crossline Pipe - Jetted 2015-306 / Port Royal Island Vacuum Truck Sub Total | 2.0 1.0 80.0 2.0 24.0 109.0 | \$47.96 \$20.46 \$1,765.79 \$47.96 \$545.43 \$2,427.60 | \$44.32 \$0.00 \$886.40 \$44.32 \$265.92 \$1,240.96 | \$0.00 \$0.00 \$292.80 \$33.50 \$85.35 \$411.65 | \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 | \$32.94 \$13.23 \$994.80 \$32.94 \$368.72 \$1,442.63 | \$125.22 \$33.69 \$3,939.79 \$158.72 \$1,265.42 \$5,522.84 |
| Grand Total | 109.0 | \$2,427.60 | \$1,240.96 | \$411.65 | \$0.00 | \$1,442.63 | \$5,522.84 |

Before




During



After



Completion: Nov-14




File:C:/sethdata/projects/projectmaps/Vac/Blackburn Pierce 2015-306



0 12.525 50 75 100 Feet

1 inch = 55 feet


Date Print: 2/10/15 File:C:/sethdata/projects/projectmaps/Vac/Campbell Rd 2015-306



0 20 40 80 120 160 Feet


1 inch = 82 feet

Prepared By: BC Stormwater Management Utility Date Print: 2/10/15 File:C:/sethdata/projects/projectmaps/Vac/Donaldson Dr 2015-306



Feet 1 inch = 97 feet

Date Print: 2/10/15 File:C:/sethdata/projects/projectmaps/Vac/Peace Haven Dr 2015-306



0 20 40 80 120 160 Feet

1 inch = 82 feet

Date Print: 2/10/15 File:C:/sethdata/projects/projectmaps/Vac/Rosieda Rd Ext 2015-306