



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Rice Road

Activity: Routine/Preventive Maintenance


Narrative Description of Project:

Completion: Oct-15

Reset (1) catch basin lid.

2016-539 / Rice Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
CBLRE / Catch Basin Lid - Reset	8.0	\$201.50	\$32.44	\$5.24	\$0.00	\$123.16	\$362.34
ONJV / Onsite Job Visit	1.0	\$30.75	\$3.54	\$3.40	\$0.00	\$18.23	\$55.92
2016-539 / Rice Road Sub Total	9.5	\$244.00	\$35.98	\$8.64	\$0.00	\$148.01	\$436.62
Grand Total	9.5	\$244.00	\$35.98	\$8.64	\$0.00	\$148.01	\$436.62

(Pictures Not Available)



Project: Rice Road

Activity: Routine/
Preventive
Maintenance














Project #:
2016-539

Township:
Port Royal Island

Completed:
October 2015

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 15 30 60 90 120
Feet

1 inch = 67 feet

Prepared By: BC Stormwater Management Utility
Date Print: 10/21/15
File: C:\project summaries map\Rice Road_2016-539