



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Charleston Drive

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired washouts.

Completion: Oct-15

2016-540 / Charleston Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
HAUL / Hauling	1.0	\$22.27	\$7.99	\$12.39	\$0.00	\$14.42	\$57.07
ONJV / Onsite Job Visit	1.0	\$30.75	\$3.54	\$1.70	\$0.00	\$18.23	\$54.22
PCAM / Pole Camera System	10.0	\$228.80	\$59.08	\$14.51	\$0.00	\$148.50	\$450.89
PRRECON / Project Reconnaissance	2.0	\$54.24	\$3.54	\$5.10	\$0.00	\$31.46	\$94.34
RPWO / Repaired Washout	17.0	\$396.90	\$24.78	\$12.18	\$0.00	\$252.16	\$686.02
UTLOC / Utility locates	0.5	\$12.35	\$0.00	\$0.00	\$0.00	\$6.62	\$18.97
2016-540 / Charleston Drive Sub Total	32.0	\$757.06	\$98.93	\$45.88	\$0.00	\$478.00	\$1,379.87
Grand Total	32.0	\$757.06	\$98.93	\$45.88	\$0.00	\$478.00	\$1,379.87

Before



After





Project: Charleston Drive

Activity: Routine/ Preventive Maintenance

Project #: 2016-540

Township: Port Royal Island

Completed: October 2015

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe

Repaired washouts.



1 inch = 67 feet

Prepared By: BC Stormwater Management Utility
 Date Print: 10/21/15
 File: C:\project summaries map\Charleston Drive_2016-540