



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Huron Drive

Activity: Routine/Preventive Maintenance

Duration: 04/10/19-04/25/19

Narrative Description of Project:

Project improved 182 L.F. of drainage system. Cleaned out 182 L.F. of roadside ditch. Installed (1) catch basin. Repaired washout. Hydroseeded for erosion control.

2019-560 / Huron Drive

	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CBINS / Catch basin - installed	30.0	\$652.55	\$206.95	\$281.08	\$0.00	\$297.00	\$1,437.58
GRDGEN / Grading - General	15.0	\$326.30	\$18.00	\$58.29	\$0.00	\$148.50	\$551.09
HAUL / Hauling	20.0	\$494.00	\$283.20	\$55.92	\$0.00	\$329.40	\$1,162.52
RSDCL / Roadside Ditch - Cleanout	30.0	\$652.60	\$111.24	\$27.49	\$0.00	\$297.00	\$1,088.33
UTLOC / Utility locates	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
2019-560 / Huron Drive Sub Total	96.5	\$2,158.14	\$619.39	\$422.79	\$0.00	\$1,071.90	\$4,272.21
Grand Total	96.5	\$2,158.14	\$619.39	\$422.79	\$0.00	\$1,071.90	\$4,272.21

Before



During



After



Project: Huron Drive

Activity: Routine/
Preventive
Maintenance

Project #:
2019-560

Township/SW Dist:
Port Royal Island/6

Completed:
April 2019



Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 20 40 80 120 160
Feet

1 inch = 83 feet

Prepared By: BC Stormwater Management Utility
Date Print: 05/29/19
File: C:\project summaries map\Huron Drive_2019-560