



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Player Road and Oakhurst Road

Activity: Routine/Preventive Maintenance

Duration: 01/30/20-03/16/20

Narrative Description of Project:

Project improved 316 L.F. of drainage system. Cleaned out 316 L.F. of roadside ditch. Replaced (1) crossline pipe.

2020-031 / Player Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CPRPL / Crossline Pipe - Replaced	42.0	\$895.76	\$225.14	\$212.48	\$0.00	\$385.98	\$1719.36
HAUL / Hauling	26.0	\$596.59	\$368.16	\$1123.93	\$0.00	\$72.10	\$2160.78
UC / Utility Coordination	1.0	\$24.70	\$0.00	\$0.00	\$0.00	\$13.23	\$37.93
UTLOC / Utility locates	1.5	\$37.05	\$0.00	\$0.00	\$0.00	\$19.85	\$56.90
2020-031 / Player Road Sub Total	71.5	\$1,575.89	\$593.30	\$1336.42	\$0.00	\$491.16	\$3,996.76
Grand Total	71.5	\$1,575.89	\$593.30	\$1336.42	\$0.00	\$491.16	\$3,996.76

(No Pictures Available)



Project: Player Road
and Oakhurst Road

Activity: Routine/
Preventive
Maintenance

Project #:
2020-031

Township/SW Dist:
Port Royal Island/6

Completed:
March 2020

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 30 60 120 180 240
Feet

1 inch = 130 feet

Prepared By: BC Stormwater Management Utility

Date Print: 04/23/20

File: C:\project summaries map\Player Road and Oakhurst Road_2020-031