## Project Summaries

June 2011

# FY 2011 Construction Project Status

<ul> <li>Potential Construction</li> </ul>	15
<ul> <li>Awaiting Easement</li> </ul>	29
<ul> <li>Engineering Support</li> </ul>	3
Awaiting Construction Start	8
Under Construction	
Compiling	
Completed	19

## FY 2011 Maintenance Projects

•	Awaiting	Maintenance	32
---	----------	-------------	----

- In Progress
- Compiling35
- Completed68



Project Summary

Project: West River Drive Completed: Sep-10

Project #: 2011-019 Project Total: \$39,585.50

Narrative Description of Project:

Project improved 288 L.F. of drainage system. Removed blockage from flowline. Grubbed, cleared and cleanout 220 L.F. of outfall ditch. Installed (2) catch basins, (1) crossline pipe, (1) access pipe and 44 L.F. outfall pipe. Jetted (3) driveway pipes, (1) crossline pipe and 24 L.F. of roadside pipe. Installed rip rap, handseeded and hydroseeded for erosion control.

### Site Photographs













Project Summary

Project: Island Tank Road Completed: Oct-10

Project #: 2011-526 Project Total: \$21,131.34

Narrative Description of Project:


Project improved 3,583 L.F. of drainage system. Grubbed and cleared 75 L.F. of workshelf. Cleaned out 400 L.F. of outfall ditch and 3,108 L.F. of roadside ditch. Installed (2) driveway pipes. Jetted (25) driveway pipes and (3) crossline pipes. Installed rip rap for erosion control.


#### Site Photographs
















Project Summary

Project: Keans Neck Road Outfall

Completed: Nov-10

Project #: 2011-524A

Project Total: \$32,605.43


Narrative Description of Project:

Project improved 3,198 L.F. of drainage system. Bush hogged and cleaned out 3,198 L.F. outfall ditch and workshelf. Installed (3) bleeder pipes. Jetted (2) crossline pipes and (2) access pipes. Installed rip rap for erosion control.











Project Summary

Project: Oree Road, Floyd Road

Completed: Dec-10


and Bull Corner Road


Project #: 2011-543

Project Total: \$31,795.00

Narrative Description of Project:

Project improved 4,310 L.F. of drainage system. Cleaned out 4,290 L.F. of roadside ditch. Installed 20 L.F. of roadside pipe. Upsized (2) crossline pipes. Replaced (1) crossline pipe to correct elevation. Installed rip rap for erosion control.







Site Photographs




After











Project Summary

Project: Warsaw Island Road Outfall

Completed: Feb-11

Project #: 2011-554

Project Total: \$29,529.31

Narrative Description of Project:

Project improved 3,964 L.F. of drainage system. Cleaned out 3,964 L.F. of

outfall ditch. Installed (1) bleeder pipe.

Before




Site Photographs



#### After







Project Summary

Project: Airport Circle Completed: Mar-11

Project #: 2011-605 Project Total: \$20,903.10

Narrative Description of Project:


Project improved 1,350 L.F. of drainage system. Cleaned out 200 L.F. of outfall ditch and 1,150 L.F. of roadside ditch. Replaced (1) crossline pipe. Installed (3) access pipes and rip rap for erosion control.

### Site Photographs



#### After







Project Summary

Project: Possum Hill Road Outfall

Completed: Apr-11


Project #: 2011-564

Project Total: \$50,872.39

Narrative Description of Project:


Project improved 1,926 L.F. of drainage system. Shinn cut and cleaned out 1,526 L.F. of outfall ditch. Constructed 400 L.F. of outfall ditch beyond critical line. Reconstructed 500 L.F. of workshelf. Installed (1) access pipe and (1) bleeder pipe. Extended (1) access pipe. Jetted (1) crossline pipe. Installed rip rap and hydroseeded for erosion control.

### Site Photographs Before During









- Roseida Rd. Extension Jul. 10 Port Royal Isl.
  - Replaced (4) storm drain covers that had been stolen.
  - -Cost \$1,032.71

- Roseida Rd. Outfall Sep. 10 Port Royal Isl.
  - Cleaned out 930 LF of outfall ditch and repaired a washout.
  - -Cost \$5,948.60

- Polite Rd. Dec. 10 Port Royal Isl.
  - Cleaned 735 LF of roadside ditch, repaired a washout & cleaned (2) crossline pipes.
  - -Cost \$4,563.99

- Ihly Farm Rd. Feb. 11 Port Royal Isl.
  - Replaced (1) crossline pipe.
  - Cost \$4,790.11

- Wimbee Landing Rd. Feb. 11 –
   Sheldon
  - Removed beaver installed blockages, replaced (1) access pipe & jetted out another.
  - Cost \$10,262.26

- Mroz Rd. Outfall Feb. 11 Port Royal Isl.
  - Removed debris from 3,370 LF of flow line by hand, bush hogged 770 LF of roadside ditch, jetted out (2) crossline pipes, cleaned out (3) inlets & (3) outlets with an excavator.
  - -Cost \$7,000.23

- County Shed Rd. Feb. 11 Port Royal Isl.
  - Repaired a catch basin & sink hole.
  - Cost \$773.41

- Lady's Isl. Bush hog Feb. 11 Lady's Isl.
  - Normal maintenance; Bush hogged 17,499 LF of outfall ditch & work shelves.
  - Cost \$9,269.34 (\$.53/If)

- St. Helena Isl. Bush Hog Mar. 11 St. Helena Isl.
  - Normal maintenance; Bush hogged
     44,899 LF of outfall ditch & workshelf,
     825 LF of roadside ditch.
  - Cost \$27,662.11 (\$.60/lf)

- Pine Grove Rd. Mar. 11 Port Royal Isl.
  - Cleaned out 1,670 LF of SCDOT roadside ditch that acts as outfall ditch for Burton Wells Rd.
  - Cost \$4,772.63