



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Salicornia Drive

**Activity:** Routine/Preventive Maintenance

**Duration:** 08/24/2022

**Narrative Description of Project:**

Project improved 91 L.F. of drainage system. Cleaned out 91 L.F. of roadside ditch.

**2023-511 / Salicornia Drive**


	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Cost</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.50	\$16.37	\$0.00	\$0.00	\$0.00	\$10.11	\$26.48
HAUL / Hauling	4.00	\$119.88	\$76.24	\$55.02	\$0.00	\$0.00	\$251.14
ONJV / Onsite Job Visit	4.00	\$166.88	\$17.40	\$9.36	\$0.00	\$0.00	\$193.64
RSDCL / Roadside Ditch - Cleanout	12.00	\$381.61	\$60.34	\$23.46	\$0.00	\$235.56	\$700.97
<b>Grand Total</b>	<b>20.50</b>	<b>\$684.74</b>	<b>\$153.98</b>	<b>\$87.84</b>	<b>\$0.00</b>	<b>\$245.67</b>	<b>\$1,172.22</b>

**Before**

**During**

**After**

**(No Picture Available)**





Project: Salicornia Drive

Activity: Routine/ Preventive Maintenance

Project #: 2023-511

Township/SW Dist: Lady's Island/7

Completed: August 2022

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe

Cleaned out 91 L.F. of roadside ditch.

0 25 50 100 150 200 Feet

1 inch = 170 feet

Prepared By: BC Stormwater Management Utility

Date Print: 12/09/22

File: C:\project summaries map\Salicornia Drive\_2023-511