



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Capehart Circle

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Removed blockages from flowline by hand.

Completion: Feb-13

2013-621 / Capehart Circle	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
RB / Remove blockage from flowline	10.0	\$233.23	\$10.05	\$6.90	\$0.00	\$159.65	\$409.83
2013-621 / Capehart Circle Sub Total	10.5	\$243.67	\$10.05	\$6.90	\$0.00	\$166.27	\$426.89
Grand Total	10.5	\$243.67	\$10.05	\$6.90	\$0.00	\$166.27	\$426.89

Before



During



After



Project: Capehart Circle

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2013-621**

**Township: Port
Royal Island**

**Completed:
February 2013**

Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe
- Parcels

Removed blockage
from flowline by hand.

CAPEHART CIR



1 inch = 43 feet