



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Indian Hill Road

**Activity:** Drainage Enhancement

**Narrative Description of Project:**

Replaced (1) driveway pipe.

**Completion:** Feb-13

2013-600 / Indian Hill Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
DPRPL / Driveway Pipe - Replaced	10.0	\$228.68	\$98.90	\$243.49	\$0.00	\$145.33	\$716.39
HAUL / Hauling	10.5	\$229.43	\$112.35	\$49.55	\$0.00	\$144.78	\$536.11
ONJV / Onsite Job Visit	2.0	\$62.44	\$8.04	\$9.00	\$0.00	\$48.94	\$128.42
<b>2013-600 / Indian Hill Road</b>	<b>23.0</b>	<b>\$530.99</b>	<b>\$219.29</b>	<b>\$302.04</b>	<b>\$0.00</b>	<b>\$345.66</b>	<b>\$1,397.97</b>
<b>Sub Total</b>							
<b>Grand Total</b>	<b>23.0</b>	<b>\$530.99</b>	<b>\$219.29</b>	<b>\$302.04</b>	<b>\$0.00</b>	<b>\$345.66</b>	<b>\$1,397.97</b>

Before



During



After





**Project: Indian Hill Road**

**Activity: Drainage Enhancement**

**Project #: 2013-600**

**Township: Sheldon**

**Completed: February 2013**

**Legend**

**TYPE**

	River
	Creek/Stream
	River/Creek/Marsh BANK
	Channel (fka Outfall)
	Channel Pipe
	Lateral
	Lateral Pipe
	Roadside
	Roadside Pipe
	Road Pipe
	Crossline Pipe
	Driveway Pipe
	Access Pipe
	Bleeder Pipe
	Parcels



1 inch = 86 feet