



## Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Bluffton Parkway

Project #: 2010-092                      Completed: Apr-10

Narrative Description of Project:

Reduced the water level in the stormwater system to allow camera pipe inspection. Cleaned out (1) catch basin. Jetted (1) crossline pipe.

**Material Cost, Rental Equipment Summary, and Labor**

Material	Unit	Cost/Unit	Qty	Cost
Water	gallon	\$0.01	750.0	\$7.50
Professional Services				\$3,300.00
Pipe Plug Rental				\$212.01
Diesel	gallon	\$2.70	104.0	\$280.80
Gas	gallon	\$2.67	33.0	\$88.11
Labor	hours		166.5	\$5,882.67
<b>Total Cost of Materials, Rental Equip., and Labor</b>				<b>\$9,771.09</b>

Note: Labor cost includes the employee's salary plus fringe benefits.

**Equipment Cost**

Item	Asset	Cost/Hour	Hrs.	Cost
Vacuum Truck	22812	\$20.30	13.0	\$263.90
6" Trash Pump	22798	\$5.95	5.0	\$29.75
Pickup Trucks		\$4.17	61.0	\$254.37
<b>Total Equipment Cost</b>				<b>\$548.02</b>

Cost/hour excludes fuel cost.

Total Cost:                      \$10,319.11

**Site Photographs**



Project: Bluffton Parkway

Activity: Drainage Emergency












Project #: 2010-092


Township: Town of Bluffton

Completed: April 2010

### Legend

#### Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder



1 inch equals 119 feet