



# Beaufort County Public Works

## Stormwater Infrastructure

### Project Summary

**Project Summary:** Browns Island Road and Gum Tree Lane

**Narrative Description of Project:**

Project improved 363 L.F. of drainage system. Removed blockage from flowline by hand. Cleaned out 363 L.F. of roadside ditch. Installed (1) access pipe and (1) access gate.

**Completion:** Mar-11

2011-625 / Browns Island Rd and Gum Tr	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Cost	Total Cost
AUDIT / Audit Project	0.50	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
HAUL / Hauling	11.50	\$244.92	\$153.07	\$74.80	\$0.00	\$0.00	\$472.79
LM / Loading Materials	0.50	\$10.71	\$14.88	\$3.40	\$0.00	\$0.00	\$28.99
RSDCL / Roadside Ditch - Cleanout	54.00	\$1,274.39	\$223.71	\$520.08	\$0.00	\$0.00	\$2,018.18
Indirect Labor, Services and Supplies	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$1,081.42	\$1,081.42
<b>2011-625 / Browns Island Rd and Gum T Sub Total</b>	<b>66.50</b>	<b>\$1,540.26</b>	<b>\$391.65</b>	<b>\$598.28</b>	<b>\$0.00</b>	<b>\$1,081.42</b>	<b>\$3,611.61</b>
<b>Grand Total</b>	<b>66.50</b>	<b>\$1,540.26</b>	<b>\$391.65</b>	<b>\$598.28</b>	<b>\$0.00</b>	<b>\$1,081.42</b>	<b>\$3,611.61</b>

Before



During



After




Project: Browns Island Road and Gum Tree Road

Activity: Drainage Maintenance

Project #: 2011-625

Township: Sheldon

Completed: March 2011



### Legend

#### Drainage Type

- River
- Stream
- Outfall
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline
- D/W
- Access
- Piped
- Bleeder
- Parcels

0 130 260 520 780 1,040 Feet

1 inch = 439 feet

Prepared By: BC Stormwater Management Utility

Date Print: 7/25/11

File:C:/sethdata/projects/projectmaps/Browns Is and Gum Tree Rd 2011-625