



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Burton Wells Road Outfall

Narrative Description of Project:

Project improved 1,610 L.F. of drainage system. Cleaned out 1,610 L.F. of outfall ditch. Installed (2) bleeder pipes. Repaired washouts.

Completion: May-11

2011-627 / Burton Wells Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Cost	Total Cost
AUDIT / Audit Project	0.50	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
BPINST / Bleeder pipe - Installed	19.00	\$446.41	\$230.44	\$443.58	\$0.00	\$0.00	\$1,120.43
HAUL / Hauling	62.00	\$1,341.69	\$825.22	\$4,736.14	\$0.00	\$0.00	\$6,903.05
LM / Loading Materials	5.50	\$117.81	\$163.63	\$36.65	\$0.00	\$0.00	\$318.08
SC / Sediment Control	2.00	\$50.50	\$4.12	\$16.31	\$0.00	\$0.00	\$70.93
WSDR / Workshelf - Dressed	87.00	\$2,016.41	\$715.30	\$171.14	\$0.00	\$0.00	\$2,902.85
Indirect Labor, Services and Supplies	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$2,754.96	\$2,754.96
2011-627 / Burton Wells Road Sub Total	176.00	\$3,983.06	\$1,938.71	\$5,403.81	\$0.00	\$2,754.96	\$14,080.53
 Grand Total	176.00	\$3,983.06	\$1,938.71	\$5,403.81	\$0.00	\$2,754.96	\$14,080.53

Before



During



After



Project: Burton Wells Road Outfall

Activity: Drainage Maintenance

Project #: 2011-627















Township: Lady's Island

Completed: May 2011



Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels

0 55 110 220 330 440 Feet

1 inch = 191 feet

Prepared By: BC Stormwater Management Utility
Date Print: 7/25/11
File:C:/sethdata/projects/projectmaps/Burton Wells Rd 2011-627