



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Cleveland Road Communications Tower Outfall

Narrative Description of Project:

Project improved 2,250 L.F. of drainage system. Bush hogged 2,250 L.F. of outfall ditch and workshelf. Cleaned out 1,250 L.F. of outfall ditch.

Completion: Jun-11

2011-640 / Cleveland Rd Communication '	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Cost	Total Cost
AUDIT / Audit Project	0.50	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
HAUL / Hauling	16.00	\$359.20	\$212.96	\$51.83	\$0.00	\$0.00	\$623.99
ODBH / Outfall ditch - bushhogged	26.00	\$556.79	\$375.04	\$68.74	\$0.00	\$0.00	\$1,000.57
ODCO / Outfall ditch - cleaned out	32.00	\$728.00	\$0.00	\$0.00	\$0.00	\$0.00	\$728.00
Indirect Labor, Services and Supplies	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$1,132.28	\$1,132.28
2011-640 / Cleveland Rd Communication Sub Total	74.50	\$1,654.23	\$588.00	\$120.57	\$0.00	\$1,132.28	\$3,495.08
Grand Total	74.50	\$1,654.23	\$588.00	\$120.57	\$0.00	\$1,132.28	\$3,495.08

Before




During



After





Cleaned out 1,250 LF of outfall ditch.

Bush hogged 2,250 LF of outfall ditch.



Project: Cleveland Drive Communications Tower Outfall

Activity: Drainage Maintenance















Project #: 2011-640

Township: Port Royal Island

Completed: June 2011

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 129 feet

Prepared By: BC Stormwater Management Utility

Date Print: 8/31/11

File: C:\sethdata\projects\projectmaps\Cleveland Dr 2011-640