



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Dolphin Point Drive

Narrative Description of Project:
Removed separated joint.

Completion: Sep-11

2012-520 / Dolphin Point Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
CLPREM / Crossline Pipe - Removed	9.0	\$196.11	\$39.79	\$22.44	\$0.00	\$0.00	\$258.34
HAUL / Hauling	3.0	\$61.44	\$39.93	\$33.80	\$0.00	\$0.00	\$135.17
PRRECON / Project Reconnaissance	7.0	\$158.89	\$12.21	\$21.63	\$0.00	\$0.00	\$192.73
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$287.98	\$287.98
2012-520 / Dolphin Point Drive Sub Total	19.5	\$426.68	\$91.93	\$77.87	\$0.00	\$287.98	\$884.46
Grand Total	19.5	\$426.68	\$91.93	\$77.87	\$0.00	\$287.98	\$884.46

Before



During



After





Project: Dolphin
Point Drive

Activity: Drainage
Maintenance

Project #:
2012-520

Township: Lady's
Island

Completed:
September 2011

Legend

Drainage Type

- River
- Stream
- Outfall
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Crossline
- D/W
- Access
- Piped
- Bleeder
- Parcels



1 inch = 128 feet