

Beaufort County Public Works
Stormwater Infrastructure
 Project Summary



Project Summary: Jasmine Hall Road and Duncan Farms Outfall

Narrative Description of Project:

Removed fallen tree from workshelf.

Completion: Jul-11

2011-645 / Jasmine Hall Road and Duncan Farms Outfall

	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
HAUL / Hauling	8.0	\$171.36	\$106.48	\$178.05	\$0.00	\$0.00	\$455.89
RMTRW / Remove trees - Workshelf	21.0	\$457.40	\$132.68	\$36.31	\$0.00	\$0.00	\$626.39
RP / Replaced Posts	6.0	\$132.60	\$8.14	\$10.01	\$180.00	\$0.00	\$330.75
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$519.64	\$519.64
2011-645 / Jasmine Hall Road and Duncan Farms Outfall	35.5	\$771.60	\$247.30	\$224.37	\$180.00	\$519.64	\$1,942.91
Grand Total	35.5	\$771.60	\$247.30	\$224.37	\$180.00	\$519.64	\$1,942.91

Before



During



After



Project: Jasmine Hall
Duncan Farms
Outfall

Activity: Drainage
Maintenance














Project #:
2011-645


Township:
Sheldon

Completed:
July 2011

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 144 feet