



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Peaches Hill Circle Outfall

Narrative Description of Project:

Project improved 3,100 L.F. of drainage system. Cleaned out 1,500 L.F. of outfall ditch and 1,600 L.F. of roadside ditch.

Completion: May-11

2011-623 / Peaches Hill Circle Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
COMP / Compile Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
HAUL / Hauling	27.0	\$585.80	\$359.37	\$254.91	\$0.00	\$0.00	\$1,200.08
RSDCL / Roadside Ditch - Cleanout	80.0	\$1,778.50	\$429.86	\$178.55	\$0.00	\$0.00	\$2,386.91
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$1,708.53	\$1,708.53
2011-623 / Peaches Hill Circle Outfall Sub Total	114.0	\$2,516.06	\$855.71	\$484.58	\$0.00	\$1,708.53	\$5,564.88
Grand Total	114.0	\$2,516.06	\$855.71	\$484.58	\$0.00	\$1,708.53	\$5,564.88

Before



After



Project: Peaches Hill Circle Outfall

Activity: Drainage Maintenance

Project #: 2011-623

Township: St. Helena Island

Completed: May 2011



Legend	
Drainage Type	
	River
	Stream
	Outfall
	Lateral
	Lateral Pipe
	Roadside
	Roadside Pipe
	Road Pipe
	Crossline
	D/W
	Access
	Piped
	Bleeder
	Parcels



1 inch = 360 feet