



# Beaufort County Public Works

## Stormwater Infrastructure

### Project Summary

**Project Summary:** Pine Grove Road Outfall

**Narrative Description of Project:**  
Removed fallen tree from workshelf.

**Completion:** Oct-11

2012-534 / Pine Grove Road Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
HAUL / Hauling	11.5	\$246.33	\$153.07	\$193.44	\$0.00	\$0.00	\$592.84
RMTRW / Remove trees - Workshelf	18.0	\$381.06	\$55.87	\$19.83	\$0.00	\$0.00	\$456.76
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$425.15	\$425.15
<b>2012-534 / Pine Grove Road Outfall Sub Total</b>	<b>30.0</b>	<b>\$637.63</b>	<b>\$208.94</b>	<b>\$213.27</b>	<b>\$0.00</b>	<b>\$425.15</b>	<b>\$1,484.98</b>
 <b>Grand Total</b>	 <b>30.0</b>	 <b>\$637.63</b>	 <b>\$208.94</b>	 <b>\$213.27</b>	 <b>\$0.00</b>	 <b>\$425.15</b>	 <b>\$1,484.98</b>

Before



During



After







Project: Pine Grove Road Outfall

Activity: Drainage Maintenance

Project #: 2012-534

Township: Port Royal Island

Completed: October 2011

**Legend**

**Drainage Type**

- River
- Stream
- Outfall
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Crossline
- D/W
- Access
- Piped
- Bleeder
- Parcels



1 inch = 56 feet