



# Beaufort County Public Works

## Stormwater Infrastructure

### Project Summary

**Project Summary:** Robinson Hill Road Outfall

**Narrative Description of Project:**

Project improved 1,598 L.F. of drainage system. Cleaned out 542 L.F. outfall ditch. Road swept 1,056 L.F. Jetted (1) crossline pipe. Hydroseeded for erosion control.

**Completion:** Jun-11

2011-633 / Robinson Hill Road Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.50	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
CLPJT / Crossline Pipe - Jetted	2.00	\$43.76	\$22.16	\$53.15	\$0.00	\$0.00	\$119.07
HAUL / Hauling	27.00	\$561.42	\$359.37	\$221.65	\$0.00	\$0.00	\$1,142.44
ODCO / Outfall ditch - cleaned out	64.50	\$1,412.99	\$325.82	\$237.31	\$0.00	\$0.00	\$1,976.12
Indirect Labor, Services and Supplies	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$1,365.92	\$1,365.92
<b>2011-633 / Robinson Hill Road Outfall</b>	<b>94.00</b>	<b>\$2,028.41</b>	<b>\$707.35</b>	<b>\$512.11</b>	<b>\$0.00</b>	<b>\$1,365.92</b>	<b>\$4,613.79</b>
<b>Grand Total</b>	<b>94.00</b>	<b>\$2,028.41</b>	<b>\$707.35</b>	<b>\$512.11</b>	<b>\$0.00</b>	<b>\$1,365.92</b>	<b>\$4,613.79</b>

Before



During



After





Project: Robinson Hill Road Outfall

Activity: Drainage Maintenance















Project #: 2011-633

Township: Sheldon

Completed: June 2011

**Legend**

**Drainage Type**

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 115 feet