



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Simmons Road Outfall

Narrative Description of Project:

Completion: Sep-11

Project improved 370 L.F. of drainage system. Cleaned out 370 L.F. of outfall ditch.

2012-524 / Simmons Road Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
ODCO / Outfall ditch - cleaned out	9.0	\$196.11	\$39.79	\$20.04	\$0.00	\$0.00	\$255.94
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$141.30	\$141.30
2012-524 / Simmons Road Outfall	9.5	\$206.35	\$39.79	\$20.04	\$0.00	\$141.30	\$407.48
Grand Total	9.50	\$206.35	\$39.79	\$20.04	\$0.00	\$141.30	\$407.48

(Pictures Not Available)

Project: Simmons Road Outfall

Activity: Drainage Maintenance














Project #: 2012-524

Township: St. Helena Island


Completed: September 2011

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels

Cleaned out 370 LF of outfall dtich.



1 inch = 194 feet