



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Browns Island Road Outfall

Narrative Description of Project:

Removed debris and repaired workshelf.

Completion: Apr-12

2012-575 / Browns Island Road Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
HAUL / Hauling	20.0	\$434.58	\$266.20	\$127.12	\$0.00	\$0.00	\$827.90
LM / Loading Materials	10.0	\$253.50	\$95.86	\$21.18	\$0.00	\$0.00	\$370.54
WSDR / Workshelf - Dressed	36.0	\$741.99	\$133.79	\$62.48	\$0.00	\$0.00	\$938.26
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$970.85	\$970.85
2012-575 / Browns Island Road Outfall Sub Total	66.5	\$1,440.31	\$495.85	\$210.78	\$0.00	\$970.85	\$3,117.79
Grand Total	66.5	\$1,440.31	\$495.85	\$210.78	\$0.00	\$970.85	\$3,117.79

(Pictures Not Available)

Project: Browns
Island Road Outfall

Activity: Drainage
Maintenance














Project #:
2012-575

Township:
Sheldon

Completed:
April 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels

Removed debris and
repaired workshelf.



0 105 210 420 630 840
Feet

1 inch = 265 feet

Prepared By: BC Stormwater Management Utility

Date Print: 5/4/12

File: C:/sethdata/projects/projectmaps/Browns Is Rd OF 12-575