

## Beaufort County Public Works Stormwater Infrastructure

Project Summary

**Project Summary:** Burton Wells Complex

**Narrative Description of Project:** 

Removed fallen tree from workshelf.

2013-512 / Burton Wells Complex	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project HAUL / Hauling RMTRW / Remove trees - Workshelf 2013-512 / Burton Wells Complex Sub Total	0.5 5.5 19.0 <b>25.0</b>	\$10.45 \$120.18 \$431.41 <b>\$562.03</b>	\$0.00 \$58.85 \$108.87 <b>\$167.72</b>	\$0.00 \$158.23 \$33.62 <b>\$191.85</b>	\$0.00 \$0.00 \$0.00 <b>\$0.00</b>	\$6.62 \$79.31 \$292.57 <b>\$378.50</b>	\$17.06 \$416.57 \$866.47 <b>\$1,300.09</b>
Grand Total	25.0	\$562.03	<b>\$167.72</b>	\$191.85	\$0.00	\$378.50	\$1,300.09

## Before







**Completion:** Jul-12

