



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Burton Wells Park

Narrative Description of Project:

Cleaned out (2) catch basins. Repaired (2) sinkholes.

Completion: Aug-12

2013-511 / Burton Wells Park	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	21.0	\$458.85	\$224.70	\$56.00	\$0.00	\$302.82	\$1,042.37
NONPRO / Non-Professional Services	0.0	\$0.00	\$0.00	\$0.00	\$1,433.49	\$0.00	\$1,433.49
PCAM / Pole Camera System	2.0	\$47.50	\$8.04	\$8.52	\$0.00	\$32.94	\$97.00
SD / Soft Digging	10.0	\$208.90	\$221.60	\$50.20	\$0.00	\$144.20	\$624.90
SR / Sinkhole repair	42.0	\$963.94	\$104.83	\$84.20	\$0.00	\$660.74	\$1,813.71
2013-511 / Burton Wells Park Sub Total	75.5	\$1,689.64	\$559.17	\$198.92	\$1,433.49	\$1,147.32	\$5,028.53
Grand Total	75.5	\$1,689.64	\$559.17	\$198.92	\$1,433.49	\$1,147.32	\$5,028.53

Before



During



After





Project: Burton Wells Complex

Activity: Drainage Maintenance

Project #: 2013-511

Township: Port Royal Island

Completed: August 2012

Cleaned out (2) catch basins and repaired (2) sink holes.

- Legend**
- Drainage Type**
- River
 - Stream
 - Outfall
 - Lateral
 - Lateral Pipe
 - Roadside
 - Roadside Pipe
 - Crossline
 - D/W
 - Access
 - Piped
 - Bleeder
 - Parcels



1 inch = 79 feet