



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Burton Wells Outfall

**Narrative Description of Project:**

Repaired workshelf. Filled potholes in (4) different locations.

**Completion:** Mar-12

<b>2012-576 / Burton Wells Outfall</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
HAUL / Hauling	14.5	\$310.59	\$193.00	\$125.59	\$0.00	\$0.00	\$629.18
RPWO / Repaired Washout	30.0	\$653.80	\$213.35	\$80.98	\$0.00	\$0.00	\$948.13
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$657.27	\$657.27
<b>2012-576 / Burton Wells Outfall</b>	<b>45.0</b>	<b>\$974.63</b>	<b>\$406.35</b>	<b>\$206.57</b>	<b>\$0.00</b>	<b>\$657.27</b>	<b>\$2,244.81</b>
<b>Sub Total</b>							
<b>Grand Total</b>	<b>45.0</b>	<b>\$974.63</b>	<b>\$406.35</b>	<b>\$206.57</b>	<b>\$0.00</b>	<b>\$657.27</b>	<b>\$2,244.81</b>

(Pictures Not Available)



Project: Burton Wells Outfall

Activity: Drainage Maintenance

Project #: 2012-576

Township: Port Royal Island

Completed: March 2012



**Legend**

**Drainage Type**

- River
- Stream
- Outfall
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Crossline
- D/W
- Access
- Piped
- Bleeder
- Parcels



1 inch = 301 feet