



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Gillison Loop Outfall

Narrative Description of Project:

Project improved 193 L.F. of drainage system. Bush hogged and cleaned out 193 L.F. of outfall ditch. Repaired washout.

Completion: Aug-12

2013-541 / Gillison Loop Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	4.0	\$87.40	\$42.80	\$18.11	\$0.00	\$57.68	\$205.99
ODBH / Outfall ditch - bushhogged	8.0	\$179.32	\$167.04	\$22.65	\$0.00	\$119.64	\$488.65
ODCO / Outfall ditch - cleaned out	6.0	\$147.39	\$28.45	\$13.44	\$0.00	\$103.53	\$292.81
2013-541 / Gillison Loop Outfall	18.5	\$424.56	\$238.29	\$54.20	\$0.00	\$287.47	\$1,004.51
Grand Total	18.5	\$424.56	\$238.29	\$54.20	\$0.00	\$287.47	\$1,004.51

Before



During



After



Project: Gillison Loop Outfall

Activity: Drainage Maintenance














Project #: 2013-541

Township: Port Royal Island

Completed: August 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 83 feet