



# Beaufort County Public Works

## Stormwater Infrastructure

### Project Summary

**Project Summary:** Harding Street Outfall

**Narrative Description of Project:**

**Completion:** Sep-12

Project improved 225 L.F. of drainage system. Remove blockage from around flapgate. Cleaned out 225 L.F. of outfall ditch.

2013-549 / Harding Street	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	8.0	\$170.96	\$85.60	\$33.00	\$0.00	\$115.36	\$404.92
ODCO / Outfall ditch - cleaned out	13.0	\$299.03	\$36.49	\$23.34	\$0.00	\$201.39	\$560.25
UTLOC / Utility locates	1.0	\$20.89	\$0.00	\$0.00	\$0.00	\$13.23	\$34.12
<b>2013-549 / Harding Street Sub Total</b>	<b>22.5</b>	<b>\$501.33</b>	<b>\$122.09</b>	<b>\$56.34</b>	<b>\$0.00</b>	<b>\$336.60</b>	<b>\$1,016.35</b>
<b>Grand Total</b>	<b>22.5</b>	<b>\$501.33</b>	<b>\$122.09</b>	<b>\$56.34</b>	<b>\$0.00</b>	<b>\$336.60</b>	<b>\$1,016.35</b>

Before



During



After





Project: Harding Street  
 Activity: Drainage Maintenance  
 Project #: 2013-549  
 Township: Port Royal Island  
 Completed: September 2012

**Legend**

**Drainage Type**

- River
- Stream
- Outfall
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Crossline
- D/W
- Access
- Piped
- Bleeder
- Parcels



1 inch = 83 feet