



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Holly Hall Road

Narrative Description of Project:

Project improved 421 L.F. of drainage system. Cleaned out 421 L.F. of outfall ditch. Jetted (2) crossline pipes.

Completion: Aug-12

2013-509 / Holly Hall Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
CLPJT / Crossline Pipe - Jetted	10.0	\$228.00	\$110.80	\$64.52	\$0.00	\$143.40	\$546.72
HAUL / Hauling	33.0	\$711.05	\$246.10	\$148.48	\$0.00	\$463.96	\$1,569.59
ODCO / Outfall ditch - cleaned out	38.0	\$896.72	\$154.62	\$64.54	\$0.00	\$615.44	\$1,731.32
2013-509 / Holly Hall Road	81.5	\$1,846.22	\$511.52	\$277.54	\$0.00	\$1,229.42	\$3,864.69
Sub Total							
Grand Total	81.5	\$1,846.22	\$511.52	\$277.54	\$0.00	\$1,229.42	\$3,864.69

Before



During



After



Project: Holly Hall Road

Activity: Drainage Maintenance














Project #: 2013-509

Township: Lady's Island

Completed: August 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels

Cleaned out 421 LF of outfall ditch.

Jetted (2) crossline pipes.



1 inch = 139 feet