



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Mint Farm Subdivision - Pond

Narrative Description of Project:

Removed debris from workshelf.

Completion: Mar-12

2012-571 / Mint Farm Subdivision - Pond	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$0.00	\$10.45
HAUL / Hauling	11.5	\$246.33	\$153.07	\$114.82	\$0.00	\$0.00	\$514.22
RMTRW / Remove trees - Workshelf	11.0	\$242.67	\$51.90	\$28.49	\$0.00	\$0.00	\$323.06
WSDR / Workshelf - Dressed	16.0	\$343.40	\$47.73	\$12.82	\$0.00	\$0.00	\$403.95
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$569.45	\$569.45
2012-571 / Mint Farm Subdivision - Pond Sub Total	39.0	\$842.85	\$252.70	\$156.13	\$0.00	\$569.45	\$1,821.12
Grand Total	39.0	\$842.85	\$252.70	\$156.13	\$0.00	\$569.45	\$1,821.12

Before



During



Project: Mint Farm Pond

Activity: Drainage Maintenance














Project #: 2012-571

Township: Port Royal Island

Completed: March 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 83 feet