



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Pickens Street Outfall

**Narrative Description of Project:**

Project improved 576 L.F. of drainage system. Removed fallen tree from workshelf. Cleaned out 576 L.F. of outfall ditch.

**Completion:** Aug-12

<b>2013-508 / Pickens Street Outfall</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	15.0	\$321.03	\$160.50	\$163.22	\$0.00	\$216.30	\$861.05
ODCO / Outfall ditch - cleaned out	21.0	\$490.14	\$150.38	\$42.88	\$0.00	\$334.18	\$1,017.58
<b>2013-508 / Pickens Street Outfall Sub Total</b>	<b>36.5</b>	<b>\$821.62</b>	<b>\$310.88</b>	<b>\$206.10</b>	<b>\$0.00</b>	<b>\$557.10</b>	<b>\$1,895.69</b>
<b>Grand Total</b>	<b>50.5</b>	<b>\$1,147.65</b>	<b>\$379.59</b>	<b>\$146.02</b>	<b>\$0.00</b>	<b>\$772.42</b>	<b>\$2,445.67</b>

Before



During



After





Project: Pickens Street

Activity: Drainage Maintenance

Project #: 2013-508

Township: Lady's Island

Completed: August 2012

Cleaned out 312 LF of outfall ditch.

Removed tree from workshelf.

Cleaned out 264 LF of outfall ditch.

### Legend

#### Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 80 feet