



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Pond Maintenance - Burton Wells Park, Shanklin Convenience Center and Sun City


Narrative Description of Project:

Completion: May-12

Bush hogged 3,453 L.F. of pond perimeter. Assist with pond evaporation device.

2012-320 / Pond Maintenance	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
PDBH / Ponds - bushhogged	33.0	\$703.84	\$420.80	\$114.75	\$0.00	\$0.00	\$1,239.39
PM / Ponds - Maintenance	25.0	\$569.70	\$40.70	\$28.32	\$0.00	\$0.00	\$638.72
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$871.82	\$871.82
2012-320 / Pond Maintenance	58.5	\$1,283.78	\$461.50	\$143.07	\$0.00	\$871.82	\$2,760.17
Sub Total							
Grand Total	58.5	\$1,283.78	\$461.50	\$143.07	\$0.00	\$871.82	\$2,760.17

(Pictures Not Available)



Project: Shanklin Road
Drop Off Center Pond
Maintenance

Activity: Drainage
Maintenance

Project #:
2012-320

Township: Port
Royal Island

Completed:
May 2012

Legend

Drainage Type

- River
- Stream
- Outfall
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Crossline
- D/W
- Access
- Piped
- Bleeder
- Parcels

Bush hogged 700 LF
of pond perimeter.

0 25 50 100 150 200
Feet

1 inch = 113 feet

Prepared By: BC Stormwater Management Utility
Date Print: 7/24/12
File: C:/sethdata/projects/projectmaps/Shanklin Drop off Pond 12-320