

Project Summary

Project Summary: Port Royal Island Vacuum Truck - Donaldson Camp Road

Narrative Description of Project: Cleaned out (2) catch basins. Jetted (1) crossline pipe.					Completion: Feb-12		
2012-306A / Port Royal Island Vacuum Truck	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project CLPJT / Crossline Pipe - Jetted Indirect Labor, Services and Supplies 2012-306A / Port Royal Island Vacuum Truck Sub Total	0.5 4.0 0.0 <b>4.5</b>	\$10.24 \$87.52 \$0.00 <b>\$97.76</b>	\$0.00 \$44.32 \$0.00 <b>\$44.32</b>	\$0.00 \$18.44 \$0.00 <b>\$18.44</b>	\$0.00 \$0.00 \$0.00 <b>\$0.00</b>	\$0.00 \$0.00 \$68.39 <b>\$68.39</b>	\$10.24 \$150.28 \$68.39 <b>\$228.91</b>
Grand Total	4.5	\$97.76	\$44.32	\$18.44	\$0.00	\$68.39	\$228.91


Before



During







1 inch = 77 feet

Date Print: 7/20/12 File:C:/sethdata/projects/projectmaps/Vac/Donaldson Camp Rd 12-306A