



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Port Royal Tree Removal - Capehart Circle

Narrative Description of Project:

Removed fallen tree from workshelf and blockage from flowline by hand.

Completion: Apr-12

2012-539A / Port Royal Tree Removal	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
RMTRW / Remove trees - Workshelf	4.0	\$80.06	\$8.14	\$10.86	\$0.00	\$0.00	\$99.06
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$59.21	\$59.21
2012-539A / Port Royal Tree Removal Sub Total	4.5	\$90.30	\$8.14	\$10.86	\$0.00	\$59.21	\$168.51
Grand Total	4.5	\$90.30	\$8.14	\$10.86	\$0.00	\$59.21	\$168.51

(Pictures Not Available)

Project: Port Royal Island Tree Removal

Activity: Drainage Maintenance














Project #: 2012-539A

Township: Port Royal Island

Completed: April 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 110 feet