



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Roseida Road

Narrative Description of Project:

Project improved 4,247 L.F. of drainage system. Cleaned out 4,247 L.F. of outfall ditch.

Completion: Mar-12

2012-536 / Roseida Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
HAUL / Hauling	49.5	\$1,059.35	\$658.85	\$167.12	\$0.00	\$0.00	\$1,885.32
ODCO / Outfall ditch - cleaned out	169.0	\$3,742.50	\$899.09	\$218.80	\$0.00	\$0.00	\$4,860.39
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$3,297.28	\$3,297.28
2012-536 / Roseida Road	219.0	\$4,812.09	\$1,557.94	\$385.92	\$0.00	\$3,297.28	\$10,053.23
Sub Total							
Grand Total	219.0	\$4,812.09	\$1,557.94	\$385.92	\$0.00	\$3,297.28	\$10,053.23

Before



During



After



Project: Roseida Road Outfall
Map 1

Activity: Drainage Management














Project #: 2012-536

Township: Port Royal Island

Completed: March 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



Cleaned out 364 LF of outfall ditch.

Cleaned out 1,031 LF of outfall ditch.

Cleaned out 220 LF of outfall ditch.



1 inch = 177 feet

Project: Roseida Road Outfall
Map 2

Activity: Drainage Maintenance














Project #:
2012-536

Township: Port
Royal Island

Completed:
March 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels

Cleaned out 1,286
LF of outfall ditch.

Cleaned out 1,346
LF of outfall ditch.

POWELL DR

LONESOME CT

MAYFIELD RD

ROSEIDA RD



1 inch = 212 feet