



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Shanklin Road Water Quality Retrofit

Narrative Description of Project:

Completion: Aug-12

Project improved 330 L.F. of drainage system. Cleaned out 330 L.F. of outfall ditch. Installed check dam for water quality.

2013-006 / Shanklin Road Water Quality Retrofit	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	9.0	\$196.65	\$85.60	\$233.39	\$0.00	\$129.78	\$645.42
ODCO / Outfall ditch - cleaned out	36.0	\$810.88	\$245.24	\$115.71	\$0.00	\$547.25	\$1,719.08
WQCD / Water Quality Check Dam	14.0	\$300.46	\$79.60	\$28.71	\$0.00	\$195.64	\$604.41
2013-006 / Shanklin Road Water Quality Retrofit : Sub Total	59.5	\$1,318.44	\$410.44	\$377.81	\$0.00	\$879.29	\$2,985.97
Grand Total	59.5	\$1,318.44	\$410.44	\$377.81	\$0.00	\$879.29	\$2,985.97

During



After





Project: Shanklin Road - Water Quality Retrofit

Activity: Drainage Improvement

Project #: 2013-006

Township: Port Royal Island

Completed: August 2012

Cleaned out 330 LF of outfall ditch. Installed check dam for water quality.

Legend

Drainage Type

- River
- Stream
- Outfall
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Crossline
- D/W
- Access
- Piped
- Bleeder
- Parcels



1 inch = 50 feet