



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Sheldon Tree Removal - Jasmine Hall Road

Narrative Description of Project:

Removed fallen tree from workshelf.

Completion: Sep-12

2013-556 / Sheldon Tree Removal	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	5.0	\$109.25	\$53.50	\$72.39	\$0.00	\$72.10	\$307.24
RMTRW / Remove trees - Workshelf	15.0	\$350.10	\$59.50	\$26.33	\$0.00	\$238.70	\$674.62
2013-556 / Sheldon Tree Removal Sub Total	20.5	\$469.80	\$113.00	\$98.72	\$0.00	\$317.41	\$998.92
Grand Total	20.5	\$469.80	\$113.00	\$98.72	\$0.00	\$317.41	\$998.92

Before



During



Project: Jasmine Hall Road - Sheldon Tree Removal

Activity: Drainage Maintenance

Project #: 2013-556














Township: Sheldon

Completed: September 2012



Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 320 feet

Prepared By: BC Stormwater Management Utility

Date Print: 10/26/12

File: C:/sethdata/projects/projectmaps/Jasmine Hall Rd 2013-556