



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Sheldon Washout Repairs - Middlefield Circle Outfall, Horace Dawson Lane Outfall and Jasmine Hall Road Outfall

**Narrative Description of Project:**

Repaired washouts.

**Completion:** Sep-12

<b>2013-544 / Sheldon - Washout Repairs</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	1.0	\$20.89	\$0.00	\$0.00	\$0.00	\$13.23	\$34.12
HAUL / Hauling	35.0	\$764.75	\$374.50	\$484.03	\$0.00	\$504.70	\$2,127.98
RPWO / Repaired Washout	36.0	\$738.74	\$209.77	\$103.19	\$0.00	\$476.28	\$1,527.98
WSREP / Workshelf - Repair	32.0	\$653.28	\$182.10	\$97.93	\$0.00	\$423.36	\$1,356.67
<b>2013-544 / Sheldon - Washout Repairs Sub Total</b>	<b>104.0</b>	<b>\$2,177.66</b>	<b>\$766.37</b>	<b>\$685.15</b>	<b>\$0.00</b>	<b>\$1,417.57</b>	<b>\$5,046.75</b>
<b>Grand Total</b>	<b>104.0</b>	<b>\$2,177.66</b>	<b>\$766.37</b>	<b>\$685.15</b>	<b>\$0.00</b>	<b>\$1,417.57</b>	<b>\$5,046.75</b>

(Pictures Not Available)

Project: Middlefield Circle Outfall - Sheldon Washout Repairs

Activity: Drainage Maintenance














Project #: 2013-544

Township: Sheldon

Completed: September 2012

### Legend

#### Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 154 feet

Project: Horace Dawson Lane  
Outfall - Sheldon  
Washout Repairs

Activity: Drainage  
Maintenance














Project #:  
2013-544

Township:  
Sheldon

Completed:  
September 2012

**Legend**

**Drainage Type**

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 241 feet

Project: Jasmine Hall Road - Sheldon Washout Repairs

Activity: Drainage Maintenance

Project #: 2013-544














Township: Sheldon

Completed: September 2012



**Legend**

**Drainage Type**

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 320 feet