



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Tanglewood Drive

Narrative Description of Project:

Repaired washout.

Completion: May-12


2012-592 / Tanglewood Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.24	\$0.00	\$0.00	\$0.00	\$0.00	\$10.24
RPWO / Repaired Washout	3.0	\$91.83	\$12.21	\$150.71	\$0.00	\$73.41	\$328.16
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$80.03	\$80.03
2012-592 / Tanglewood Drive	3.5	\$102.07	\$12.21	\$150.71	\$0.00	\$153.44	\$418.43
Sub Total							
Grand Total	3.5	\$102.07	\$12.21	\$150.71	\$0.00	\$153.44	\$418.43

Before



After





Project: Tanglewood Drive

Activity: Drainage Maintenance














Project #: 2012-592

Township: Port Royal Island

Completed: May 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 83 feet