



Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Thomas Sumpter Street Outfall

Narrative Description of Project:

Project improved 597 L.F. of drainage system. Cleaned out 365 L.F. of outfall ditch. Repaired washouts. Jetted 232 L.F. of outfall pipe.

Completion: Mar-12

2012-570 / Thomas Sumpter Street Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$20.48	\$0.00	\$0.00	\$0.00	\$0.00	\$20.48
HAUL / Hauling	30.0	\$661.20	\$399.30	\$577.06	\$0.00	\$0.00	\$1,637.56
ODCO / Outfall ditch - cleaned out	35.0	\$793.20	\$171.37	\$72.23	\$0.00	\$0.00	\$1,036.80
OFPJ / Outfall Pipe - Jetted	20.0	\$437.60	\$221.60	\$85.20	\$0.00	\$0.00	\$744.40
RPWO / Repaired Washout	20.0	\$449.00	\$95.86	\$5,090.75	\$0.00	\$0.00	\$5,635.61
WSREC / Workshelf - Reconstructed	5.0	\$126.75	\$20.60	\$13.44	\$0.00	\$0.00	\$160.79
Indirect Labor, Services and Supplies	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$1,714.15	\$1,714.15
2012-570 / Thomas Sumpter Street Outfall Sub Total	111.0	\$2,488.23	\$908.73	\$5,838.68	\$0.00	\$1,714.15	\$10,949.79
Grand Total	111.0	\$2,488.23	\$908.73	\$5,838.68	\$0.00	\$1,714.15	\$10,949.79

Before



During



After



Project: Thomas Sumpter Street Outfall

Activity: Drainage Maintenance

Project #: 2012-570

Township: Lady's Island

Completed: March 2012

Legend

Drainage Type

-  River
-  Stream
-  Outfall
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Crossline
-  D/W
-  Access
-  Piped
-  Bleeder
-  Parcels



1 inch = 164 feet