



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Campbell Road

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

**Completion:** Aug-13

Project improved 100 L.F. of drainage system. Cleaned out 100 L.F. of roadside ditch. Replaced (1) crossline pipe. Installed rip rap for erosion control

2013-639 / Campbell Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CPRPL / Crossline Pipe - Replaced	30.0	\$674.89	\$135.98	\$316.39	\$0.00	\$451.80	\$1,579.06
HAUL / Hauling	14.0	\$302.78	\$149.80	\$541.13	\$0.00	\$201.88	\$1,195.59
ONJV / Onsite Job Visit	5.0	\$159.21	\$18.10	\$8.88	\$0.00	\$109.87	\$296.06
PP / Project Preparation	6.0	\$134.98	\$7.24	\$3.29	\$0.00	\$90.36	\$235.87
PRRECON / Project Reconnaissance	2.0	\$80.46	\$8.04	\$8.88	\$0.00	\$67.92	\$165.30
UTLOC / Utility locates	1.0	\$20.68	\$0.00	\$0.00	\$0.00	\$13.23	\$33.91
<b>2013-639 / Campbell Road Sub Total</b>	<b>58.5</b>	<b>\$1,383.23</b>	<b>\$319.16</b>	<b>\$878.57</b>	<b>\$0.00</b>	<b>\$941.68</b>	<b>\$3,522.64</b>
<b>Grand Total</b>	<b>58.5</b>	<b>\$1,383.23</b>	<b>\$319.16</b>	<b>\$878.57</b>	<b>\$0.00</b>	<b>\$941.68</b>	<b>\$3,522.64</b>

Before



During



After





**Project: Campbell Road**

**Activity: Routine/ Preventive Maintenance**

**Project #: 2013-639**

**Township: Port Royal Island**

**Completed: August 2013**

**Legend**

- Catch Basin
- TYPE**
- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe



**1 inch = 55 feet**