

Beaufort County Public Works

Stormwater Infrastructure

Project Summary

Project Summary: Chisholm Hill Road Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project: Completion: Dec-13

Project improved 6,045 L.F. of drainage system. Bush hogged 6,045 L.F. of channel. Cleaned out 3,860 L.F. of channel.

2014-547 / Chisholm Hill Road Channel #1	Labor	Labor	Equipment	Material	Contractor	Indirect	
	Hours	Cost	Cost	Cost	Cost	Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	13.0	\$281.19	\$139.10	\$56.61	\$0.00	\$187.46	\$664.36
ODBH / Outfall ditch - bushhogged	60.0	\$1,227.15	\$1,077.20	\$170.73	\$0.00	\$432.60	\$2,907.68
ODCO / Outfall ditch - cleaned out	90.0	\$1,962.00	\$374.68	\$117.39	\$0.00	\$1,300.50	\$3,754.57
ONJV / Onsite Job Visit	6.0	\$192.40	\$21.72	\$23.36	\$0.00	\$134.34	\$371.82
PP / Project Preparation	10.0	\$222.20	\$18.10	\$2.92	\$0.00	\$133.35	\$376.57
2014-547 / Chisholm Hill Road Channel #1	179.5	\$3,895.17	\$1,630.80	\$371.01	\$0.00	\$2,194.86	\$8,091.84
Sub Total							
Grand Total	179.5	\$3,895.17	\$1,630.80	\$371.01	\$0.00	\$2,194.86	\$8,091.84







After



