



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Burton Wells Complex

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired washout.

Completion: Feb-13

2013-610 / Burton Wells Complex	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
ONJV / Onsite Job Visit	1.0	\$25.65	\$4.02	\$3.12	\$0.00	\$18.23	\$51.02
RPWO / Repaired Washout	10.5	\$233.42	\$14.07	\$30.24	\$0.00	\$112.42	\$390.15
2013-610 / Burton Wells Complex Sub Total	12.0	\$269.51	\$18.09	\$33.36	\$0.00	\$137.27	\$458.23
Grand Total	12.0	\$269.51	\$18.09	\$33.36	\$0.00	\$137.27	\$458.23

Before



During



After



Project: Burton Wells Complex

Activity: Routine/
Preventive
Maintenance
















Project #:
2013-610

Township: Port
Royal Island

Completed:
February 2013

Legend

Drainage Type

-  River
-  River/Creek/Marsh Bank
-  Creek/Stream
-  Channel (fka Outfall)
-  Channel Pipe
-  Roadside
-  Road Pipe
-  Roadside Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels



Repaired washout.



D/W

MIDDLETON RECREATION DR

POITE DR



1 inch = 107 feet