



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Port Royal Island Tree Removal - Chisholm Hill Road Outfall, Bay Pines Road Outfall, Burton Wells Complex Outfall and Mint Farm Pond

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Removed fallen tree from workshelf. Repaired washout.

Completion: Feb-13

2013-551B / Port Royal Island Tree Removal	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	5.0	\$109.25	\$53.50	\$222.24	\$0.00	\$72.10	\$457.09
RMTRW / Remove trees - Workshelf	47.0	\$1,052.60	\$146.86	\$101.78	\$0.00	\$617.24	\$1,918.48
2013-551B / Port Royal Island Tree Removal Sub Total	52.5	\$1,172.30	\$200.36	\$324.02	\$0.00	\$695.96	\$2,392.63
Grand Total	52.5	\$1,172.30	\$200.36	\$324.02	\$0.00	\$695.96	\$2,392.63

Before



After




Project: PRI Tree Removal - Chisholm Hill Road Outfall

Activity: Routine/ Preventive Maintenance

Project #: 2013-551B

Township: Port Royal Island

Completed: Febuary 2013



Legend	
Drainage Type	
	River
	River/Creek/Marsh Bank
	Creek/Stream
	Channel (fka Outfall)
	Channel Pipe
	Roadside
	Road Pipe
	Roadside Pipe
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	Access Pipe
	Bleeder Pipe
	Parcels



1 inch = 202 feet

Prepared By: BC Stormwater Management Utility
Date Print: 3/20/13
File:C:/sethdata/projects/projectmaps/Chisholm Hill Rd OF 2013-551B


Project: PRI Tree Removal - Bay Pines Road Outfall

Activity: Routine/ Preventive Maintenance

Project #: 2013-551B
















Township: Port Royal Island

Completed: Febuary 2013



Legend

Drainage Type

-  River
-  River/Creek/Marsh Bank
-  Creek/Stream
-  Channel (fka Outfall)
-  Channel Pipe
-  Roadside
-  Road Pipe
-  Roadside Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels



1 inch = 345 feet



Project: PRI Tree Removal -Burton Wells Complex

Activity: Routine/ Preventive Maintenance

Project #: 2013-551B
















Township: Port Royal Island

Completed: February 2013

Removed fallen tree from the workshelf.


Legend

Drainage Type

-  River
-  River/Creek/Marsh Bank
-  Creek/Stream
-  Channel (fka Outfall)
-  Channel Pipe
-  Roadside
-  Road Pipe
-  Roadside Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels



1 inch = 500 feet



Removed fallen trees from around pond.

Project: PRI Tree Removal -Mint Farm Pond

Activity: Routine/ Preventive Maintenance

Project #: 2013-551B

Township: Port Royal Island

Completed: February 2013

Legend

Drainage Type

- River
- River/Creek/Marsh Bank
- Creek/Stream
- Channel (fka Outfall)
- Channel Pipe
- Roadside
- Road Pipe
- Roadside Pipe
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- Access Pipe
- Bleeder Pipe
- Easements
- Parcels



1 inch = 102 feet