

## Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Walker Circle

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Removed blockage from flowline.

2014-511 / Walker Circle	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	<b>Total Cost</b>
AUDIT / Audit Project HAUL / Hauling RB / Remove blockage from flowline 2014-511 / Walker Circle Sub Total	0.5 4.0 6.0 <b>10.5</b>	\$10.23 \$86.52 \$134.98 <b>\$231.73</b>	\$0.00 \$42.80 \$23.87 <b>\$66.67</b>	\$0.00 \$29.61 \$16.45 <b>\$46.06</b>	\$0.00 \$0.00 \$0.00 <b>\$0.00</b>	\$6.62 \$57.68 \$90.36 <b>\$154.66</b>	\$16.85 \$216.61 \$265.66 <b>\$499.11</b>
Grand Total	10.5	\$231.73	\$66.67	\$46.06	\$0.00	\$154.66	\$499.11





During



After

**Completion:** Jul-13



