

## Beaufort County Public Works

## Stormwater Infrastructure

Project Summary

Project Summary: Burton Wells Sports Complex

Activity: Routine/Preventive Maintenance

Narrative Description of Project: Completion: Jun-13

Project improved 10 L.F. of drainage system. Removed blockage from flowline by hand. Jetted 10 L.F. of channel pipe.

2013-653 / Burton Wells Sports Complex	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project ONJV / Onsite Job Visit PRRECON / Project Reconnaissance RB / Remove blockage from flowline 2013-653 / Burton Wells Sports Complex Sub Total	0.5 4.0 2.0 15.0 <b>21.5</b>	\$10.45 \$124.88 \$80.46 \$341.60 \$557.39	\$0.00 \$16.08 \$8.04 \$42.19 <b>\$66.31</b>	\$0.00 \$9.00 \$12.00 \$19.32 <b>\$40.32</b>	\$0.00 \$0.00 \$0.00 \$0.00 <b>\$0.00</b>	\$6.62 \$97.88 \$67.92 \$163.40 <b>\$335.82</b>	\$17.06 \$247.84 \$168.42 \$566.51 <b>\$999.83</b>
Grand Total	21.5	\$557.39	\$66.31	\$40.32	\$0.00	\$335.82	\$999.83

## Before



During



After



