



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Hunters Grove Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Jun-13

Project improved 28 L.F. of drainage system. Replaced 28 L.F. of channel pipe and reinstalled rip rap for erosion control.

2013-649 / Hunters Grove Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	5.0	\$104.45	\$53.50	\$10.61	\$0.00	\$66.15	\$234.71
OFPI / Outfall Pipe - Installation	24.0	\$550.08	\$102.92	\$369.09	\$0.00	\$239.40	\$1,261.49
ONJV / Onsite Job Visit	5.0	\$123.05	\$20.10	\$12.00	\$0.00	\$91.15	\$246.30
PRRECON / Project Reconnaissance	2.0	\$80.46	\$8.04	\$9.00	\$0.00	\$67.92	\$165.42
UTLOC / Utility locates	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
2013-649 / Hunters Grove Road Sub Total	37.0	\$878.93	\$184.56	\$400.70	\$0.00	\$477.85	\$1,942.04
 Grand Total	 37.0	 \$878.93	 \$184.56	 \$400.70	 \$0.00	 \$477.85	 \$1,942.04

Before



During



After





Project: Hunters Grove Road

Activity: Routine/ Preventive Maintenance

**Project #:
2013-649**

Township: St. Helena Island

**Completed:
June 2013**

Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe
- Catch Basin



1 inch = 58 feet