



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Oakhurst Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 60 L.F. of drainage system. Backfilled 60 L.F. of channel.

Completion: Jun-13

2013-654 / Oakhurst Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
BKFILL / Back Fill	10.0	\$228.62	\$134.28	\$18.28	\$0.00	\$79.38	\$460.56
HAUL / Hauling	4.0	\$87.40	\$42.80	\$42.81	\$0.00	\$57.68	\$230.69
ONJV / Onsite Job Visit	2.0	\$49.22	\$8.04	\$9.30	\$0.00	\$36.46	\$103.02
2013-654 / Oakhurst Road Sub Total	16.5	\$375.69	\$185.12	\$70.39	\$0.00	\$180.14	\$811.33
Grand Total	16.5	\$375.69	\$185.12	\$70.39	\$0.00	\$180.14	\$811.33

(Pictures Not Available)

Project: Oakhurst Road

**Activity: Routine/
Preventive
Maintenance**















**Project #:
2013-654**

**Township:
Sheldon**

**Completed:
June 2013**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 280 feet