



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Cherokee Farms Road Outfall

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 1,725 L.F. of drainage system. Cleaned out 1,725 L.F. of channel. Repaired washout.

**Completion:** Mar-13

2013-601 / Cherokee Farms Road Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	64.0	\$1,398.40	\$735.33	\$345.65	\$0.00	\$898.57	\$3,377.95
ODCO / Outfall ditch - cleaned out	145.0	\$3,276.17	\$1,015.54	\$205.07	\$0.00	\$2,074.00	\$6,570.78
ONJV / Onsite Job Visit	13.0	\$378.33	\$52.26	\$34.01	\$0.00	\$290.16	\$754.76
RPWO / Repaired Washout	26.0	\$600.42	\$162.42	\$33.75	\$0.00	\$388.04	\$1,184.63
<b>2013-601 / Cherokee Farms Road Outfall</b>	<b>248.5</b>	<b>\$5,663.77</b>	<b>\$1,965.55</b>	<b>\$618.48</b>	<b>\$0.00</b>	<b>\$3,657.38</b>	<b>\$11,905.17</b>
<b>Grand Total</b>	<b>248.5</b>	<b>\$5,663.77</b>	<b>\$1,965.55</b>	<b>\$618.48</b>	<b>\$0.00</b>	<b>\$3,657.38</b>	<b>\$11,905.17</b>

Before



During



After





**Project: Cherokee Farms Road**

**Activity: Routine/ Preventive Maintenance**

**Project #: 2013-601**

**Township: Port Royal Island**

**Completed: March 2013**



**Legend**

**TYPE**

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe

0 60 120 240 360 480 Feet

1 inch = 230 feet

Prepared By: BC Stormwater Management Utility

Date Print: 6/20/13

File:C:/sethdata/projects/projectmaps/Cherokee Farms 2013-601