



Beaufort County Public Works *Stormwater Infrastructure* Project Summary

Project Summary: Chisholm Hill Road Outfall

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 570 L.F. of drainage system. Removed blockage from flowline by hand. Cleaned out 570 L.F. of channel.

Completion: Mar-13

2013-608 / Chisholm Hill Road Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
BPR / Bleeder Pipe - Removed	12.0	\$266.76	\$32.47	\$17.45	\$0.00	\$128.48	\$445.16
HAUL / Hauling	24.5	\$535.33	\$262.15	\$94.45	\$0.00	\$331.19	\$1,223.12
ODCO / Outfall ditch - cleaned out	30.0	\$666.90	\$122.15	\$44.12	\$0.00	\$321.20	\$1,154.37
ONJV / Onsite Job Visit	2.0	\$49.22	\$8.04	\$3.12	\$0.00	\$36.46	\$96.84
RB / Remove blockage from flowline	6.0	\$136.70	\$8.04	\$6.24	\$0.00	\$91.76	\$242.74
2013-608 / Chisholm Hill Road Outfall Sub Total	75.0	\$1,665.35	\$432.85	\$165.38	\$0.00	\$915.71	\$3,179.28
Grand Total	75.0	\$1,665.35	\$432.85	\$165.38	\$0.00	\$915.71	\$3,179.28

Before



After



